



July 2008

Mr. XX XXX

Street Address

City, State Zip

Dear teutonia User:

This letter is an important safety notice about your teutonia stroller seat, AT06BLK.

There are two stickers on the sides of the seat unit that need to be removed and discarded immediately. These labels are not intended for this seat. The attached picture diagrams show the location of these labels.

If you have any further questions about this safety notice please contact the teutonia customer service team at 1.877.teutonia or visit our website at [www.teutoniausa.com](http://www.teutoniausa.com) – click on the *product owner* section.

Thank you for your attention to this matter. We apologize for any inconvenience this may cause you.

Sincerely,  
teutonia USA

Model # AT06BLK – t-stroller seat



Right side label  
"CAUTION! ...."



Left side label  
"ACHTUNG! ...."



Remove the  
silver labels from  
both sides and  
discard



Seat without  
labels

